


FIG. 1



CREDIT 50

WIN 0





FIG. 3a


CREDIT 50

WIN 0

FIG. 3b

CREDIT 50

WIN 0



CURRENT
LEVEL

36

FIG. 3c

CREDIT 50

WIN 0




FIG. 3d

CREDIT 50

WIN 0





FIG 4a

CREDIT 50

WIN 28




FIG. 4b.




70

Fig. 5a




70

Fig. 5b



70

Fig. 5c



70

Fig. 5d

8/10

XYZ CONSTRUCTION INC.

SHARE VALUE: 5.00

BROKERS TIPS: A good, sound buy

SHARE HISTORY: Not much movement

RECENT HEADLINES: n/a

ABC MINING CO.

SHARE VALUE 5.00

BROKERS TIPS: A risky venture

SHARE HISTORY: Volatile movement

RECENT HEADLINES: "ABC Mining
Strikes Gold"

80




FIG. 6

Vertical text on the left margin, likely a scanning artifact or page number.

FIG. 7 is a perspective view of the display of FIG. 6, showing the display in a position where the display is used to display information.

90

88



VALUE:

5.00

HEADLINES:

ABC MINING STRIKES GOLD

OF SHARES:


30


84

FIG. 7

9/10

182

FIG 8






FIG 10